

Comments:	The geotechnical report does not meet the City of Mission requirements. A reference plan will be required for the slope edge and geotechnical set back. A well report will be required for the second lot A record of sewerage will be required for the second lot Fire intertace area. Easement agreements need to be created for the driveway if shared as well as for the power poles. Fire decartment turn around required for the new lot
Signature	Muchene Colde
Name:	Michael Rohde
Department or Organization:	Inspection Services
Date:	February 9, 2022